RC 10(S)/2024/(1)
TMR NO. 71/24

CENTRAL BUREAU OF INVESTIGATION
SP-I/SC-I
Diary No. 1919
Dated 12.9.24

CENTRAL FORENSIC SCIENCE LABORATORY
DIRECTORATE OF FORENSIC SCIENCE SERVICES
MINISTRY OF HOME AFFAIRS, GOVT. OF INDIA
Block No. 4, CGO Complex, Lodhi Road
New Delhi-110003

D-75


Crime Scene Examination Report

Report No: CFSL/DELHI/1648 /BIO/90/24/3289 **Dated: 11.09.2024**

1.	Forwarding Authority:	The Supdt. of Police, CBI, SC - 1, New Delhi.
2.	Reference:	Letter No. Case 1644 / RC / 10 (S) / 2024 / CBI / SC.1 / ND. Dated: 13.08.2024
3.	RC no.	RC10 (S) / 2024 / CBI / SC-1 / New Delhi Dated: 13.08.2024
4.	Place &date of occurrence:	R G Kar Medical Collage& Hospital, Kolkata, 09-08-2024 (night)
5.	Date of visit:	14.08.2024 from 03.50 PM to 7.30 PM
6.	Expert team deputed by Director, CFSL, Delhi:	Dr. B K Mohapatra, DD (Biology) - Head of CFSL team Sh. A D Tiwari, DD (Photo) Sh. P K Gottam, DD (Photo) Sh. Anuj Kumar Bhati, AD (Finger Print) Sh. Mithilesh Jha, Scientist - B (Biology)

7. Background of this case [Forensic relevance]:

The Scene of Crime was related to alleged rape & murder of a trainee lady doctor of R G Kar Medical College & Hospital Kolkata, in the hospital itself. It was informed that the body of the lady doctor was found, lying dead with multiple injuries and blood on a mattress [inside the seminar hall], on the third floor of R G Kar Medical college, in the morning hours. That scene itself created doubt amid hospital staff of sexual violence cum murder of the lady doctor inside the hospital building. The Post Mortem of the victim body was already conducted by the Department of Forensic Medicine R G Kar Medical College & Hospital Kolkata; and the dead body was cremated thereof. CFSL team was informed that SOC was already visited and examined by the SIT, Kolkata Police and the evidentiary exhibits were taken into their custody and sent for the laboratory examination at CFSL, Kolkata. In the meanwhile, this case become highly sensitive in nature & there was a lot of public uproar throughout the nation, this brought down activities of major hospitals of the country to a partially stalled condition [as majority of staffs went on strike for demand of justice].



SOC: Dept. of Respiratory Medicine, RG Kar Medical College & Hospital, Kolkata/huge public under protest [just outside SOC] spreading more than 600meters

Henceforth, the Hon'ble Kolkata High Court taking cognizance of the nationwide public uproar transferred this case to CBI [vide W.P (P) No: 332 / 2024 dated: 13.08.2024]. On 13.08.2024 evening vide letter 1644 / RC / 10 (S) / 2024 / CBI/ SC.1/ ND/13.08.2024 the CBI sought the scientific assistance from the Director, CFSL, Delhi in their Investigation. Accordingly, the nominated forensic expert team reached Kolkata on 14.08.2024 morning; visited and examined the SOC [along with CBI team] on the same day. The SOC was not in well preserved condition, there were evidences of disturbances evident on the scene. The team forensically meditated on the given inputs vis-à-vis actual SOC condition.

8. Forensic Observations of the Scene of Crime on 14.08.2024 made by the CFSL Delhi team:

i. The forensic team of Delhi got its preliminary in-puts from the CBI team, local official attendees present at the R G Kar Medical College & Hospital, Kolkata.

ii. The Post Mortem of the victim' body was already conducted by the Department of Forensic Medicine R G Kar Medical College & Hospital Kolkata.

iii. The team was informed that the victim' body was already cremated.

iv. CFSL team was also informed that SOC was already visited and examined by the SIT, Kolkata Police.


CENTRAL FORENSIC SCIENCE LABORATORY
DIRECTORATE OF FORENSIC SCIENCE SERVICES
MINISTRY OF HOME AFFAIRS, GOVT. OF INDIA
Block No. 4, CGO Complex, Lodhi Road
New Delhi-110003

Crime Scene Examination Report


Report No: CFSL/DELHI/1648 /BIO/90/24/..7389 Dated: ..11.09.2024

v. The evidentiary exhibits were taken into SIT, Kolkata Police custody & were forwarded for the laboratory examination at CFSL, Kolkata.


CFSL Delhi team minutely and forensically evaluated on the given inputs vis-à-vis left-over clues at the disturbed scene; the forensic observations were meditated upon and the plausible forensic inferences [of relevance to the Investigation & Justice] are summarized as below:



Huge public uproar



Patient wards



Inside TB Ward

vi. There was huge public uproar and huge media presence observed by the team at the entrance to the ground floor of the R G Kar Medical College & Hospital Kolkata.

vii. CFSL team passed through this massive public rush into the hospital premises with the help of CRPF and the local police; from here team moved to the third floor via main lift.


viii. Hospital corridor [extending from the main lift area of the third floor] was leading to the TB ward; the ward was having hospital staff, Inhouse patients and attendants.

ix. CFSL team observed that the nursing station inside the TB ward was a hall of about 30 ft X 30 ft dimension, this nursing station was meant for round the clock TB ward operations.

x. CFSL team observed that the entrance to the seminar hall was invariably to be made through the nursing station (as stated by hospital staffs).

xi. For this reason, chance of anybody by passing it to Seminar Hall [the SOC] was forensically evaluated.

xii. The Seminar Hall [the SOC] was found inside the TB ward, located at the third floor, it was not an isolated palace; in the way to Seminar Hall [the SOC] there was 24x7 nursing station; there after passing along with the patient rooms / wards on one side of the main corridor.



(3)

CENTRAL FORENSIC SCIENCE LABORATORY
DIRECTORATE OF FORENSIC SCIENCE SERVICES
MINISTRY OF HOME AFFAIRS, GOVT. OF INDIA
Block No. 4, CGO Complex, Lodhi Road
New Delhi-110003


Crime Scene Examination Report

Report No: CFSL/DELHI/1648 /BIO/90/24/3389 Dated: 11. 09.2024

xlii. During the SOC examination the CFSL team observed that 24x7 nursing station [enroot to the SOC] area was found functioning and five nursing staffs were performing their duties of attending inhouse patients: the same was forensically observed in context to the CBI investigation sought by the Hon'ble High Court.

xiv. Further, emergency medicines and medical care devices and equipment, registers and other documents were also found to be kept at the nursing station area.


xv. The Investigation Officer of CBI of this case was advised to go through the contents of available documents at the nursing station for relevant information related to this incident.




xvi. The nursing station side was further allowing a narrow corridor leading to the Respiratory care unit Dept of Pulmonary Medicine; that was further leading to the SOC seminar hall.

xvii. As per the hospital staffs, this narrow corridor is meant to follow/ being followed by all people/public for entering into the dept of Respiratory care unit Dept of Pulmonary Medicine of R J Kar Medical College.

xviii. On the left side of this narrow corridor there was resident doctor's room[s] amid the rooms of HOD Dept of pulmonary medicine, library room, etc.






xix. Hence-forth, chances of anybody by-passing all of attendees in these 24x7 operational areas on-to the Seminar Hall [the SOC] were also evaluated forensically.

(4)

CENTRAL FORENSIC SCIENCE LABORATORY
DIRECTORATE OF FORENSIC SCIENCE SERVICES
MINISTRY OF HOME AFFAIRS, GOVT. OF INDIA
Block No. 4, CGO Complex, Lodhi Road
New Delhi-110003

Crime Scene Examination Report


Report No: CFSL/DELHI/1648 /BIO/90/24/2389 Dated: 11.09.2024



xx. The toilets found on the starting point of the corridor were found to be in a broken condition: area evaluated forensically by the CFSL team.



xxi. The wall and floor tiles of the said toiles were found removed: area evaluated forensically by the CFSL team



xxii. Two side walls of first room (window AC was installed in this room) on the corridor towards left were found to be unbelievably smashed condition in unprofessional manner.

xxiii. Evaluated forensically by the CFSL, Delhi team


(5)

CENTRAL FORENSIC SCIENCE LABORATORY
DIRECTORATE OF FORENSIC SCIENCE SERVICES
MINISTRY OF HOME AFFAIRS, GOVT. OF INDIA
Block No. 4, CGO Complex, Lodhi Road
New Delhi-110003


Crime Scene Examination Report

Report No: CFSL/DELHI/1648 /BIO/90/24/.3389 **Dated: 11.09.2024**

xxiv. Here one demolished wall was evidently corresponding pre-presence of a door area, another demolished wall area was having fixed & functional electric peripherals and as such did not correspond to pre-presence of a particular passage: same were evaluated forensically by the CFSL team.



xxv. The concrete materials, building materials, broken tiles were found scattered on the floor of the said rooms and corridor also evaluated forensically by the CFSL team.



xxvi. The adjacent room [meant for inhouse doctors' rest purposes] was also found to be demolished in unprofessional manner, here, its wall was found smashed that was corresponding to an entry gate: evaluated forensically by the CFSL team.

xxvii. In this rest room some patient beds and wooden furniture with dirty mattresses/ bed sheets were kept haphazardly, whereas, demolished concrete material was not found.

xxviii. These areas were evaluated forensically by the CFSL team.


xxix. The two wooden gate frames [stated to be removed] were found to be kept in front of the demolished wall of the 1st Room in the corridor area; IO was suggested to take the notice of it [as part of the investigation].

(6)


CENTRAL FORENSIC SCIENCE LABORATORY
DIRECTORATE OF FORENSIC SCIENCE SERVICES
MINISTRY OF HOME AFFAIRS, GOVT. OF INDIA
Block No. 4, CGO Complex, Lodhi Road
New Delhi-110003

Crime Scene Examination Report

Report No: CFSL/DELHI/1648 /BIO/90/24/.3389 Dated: .11. 09.2024



A: Demolished wall in the 1st Room corresponding to door	B: Demolished wall in the 2nd Room corresponding to door	C: View of Seminar Hall from 1st Room.	D: Unusually demolished wall having hanging functional electric peripherals in the 1st Room



View of [illegible] [Seminar Hall] as observed [illegible] Room. Detached [illegible] was found kept inside the pulmonary med dept. room.

xxx. The seminar room was situated on the right side of the corridor of respiratory care unit Department of Pulmonary Medicine, evaluated forensically by the CFSL team.

xxxi. The seminar room was having five entry doors, all entry doors were facing to the corridor. However, it was conveyed by the hospital staffs that only the first door was in operation for entry/ exit purpose and the rest of


(7)

CENTRAL FORENSIC SCIENCE LABORATORY
DIRECTORATE OF FORENSIC SCIENCE SERVICES
MINISTRY OF HOME AFFAIRS, GOVT. OF INDIA
Block No. 4, CGO Complex, Lodhi Road
New Delhi-110003

Crime Scene Examination Report

Report No: CFSL/DELHI/1648 /BIO/90/24/3389 Dated: 11.09.2024


the doors [including the four inside] remain in closed condition; the same was verified by the CFSL team.




xxxii. Team also observed that the entry door [first one] of the seminar hall was found in locked condition with a cloth piece tied on it, however, team observed that the lock was not further officially sealed with lac seal.

xxxiii. This lock was opened in presence of the CBI officials as well as the CBI Independent witnesses in the presence of CFSL team.

9. Forensic examination inside the Seminar Hall on 14.08.2024: The relevant scientific observations in continuation of above are as follows:



xxxii. Inside the seminar hall [opposite side to the entry door] there were four doors stated to be remained closed; IO was suggested to take the notice of it [as part of the investigation].




xxxiii. There was a wooden stage of about 10ft X 15 ft dimension at one end of the Seminar Room; this is the spot where the hospital authorities told to CBI that the said crime occurred here.

xxxiv. This wooden stage in the seminar hall was found shielded [with a white cloth ward screen] in as such a way that it can only be visible on reaching nearby the stage.

CENTRAL FORENSIC SCIENCE LABORATORY
DIRECTORATE OF FORENSIC SCIENCE SERVICES
MINISTRY OF HOME AFFAIRS, GOVT. OF INDIA
Block No. 4, CGO Complex, Lodhi Road
New Delhi-110003

Crime Scene Examination Report

Report No: CFSL/DELHI/1648 /BIO/90/24/3289 Dated: 11.09.2024




xxxv. Evaluated forensically by the CFSL, Delhi team.

xxxvi. Team observed an unobstructed bare mattress with white cover having large sized cut marks at two places found on the end of wooden stage just aligning the wall having the hanged projector screen and a broken light panel of X-ray viewer board beside and aligning the mattress on which the said crime was stated to have occurred.

xxxvii. In between [the mattress lying on the wooden stage and the shielding white cloth ward screen] there was a long wooden table with a blue plastic sheet top.

xxviii. This wooden table was found parallelly aligned to both the screen as well as the mattress inside the seminar hall in which the said crime was stated to have occurred; areas on, underneath adjacent the wooden stage Evaluated forensically by the CFSL, Delhi team.




xxxix. Besides that, this seminar hall was having many in use red coloured and some blue coloured plastic & cushioned chairs [with iron frame(s)], wooden chairs, wooden sitting bench, computer systems, CPU, projector devices, some medical equipment.


xl. Apart from these items the seminar hall on the opposite side of the wooden stage was having stack(s) of several mattresses, bed sheets, blankets, unused equipment & old items were found in dumped condition.

CENTRAL FORENSIC SCIENCE LABORATORY
DIRECTORATE OF FORENSIC SCIENCE SERVICES
MINISTRY OF HOME AFFAIRS, GOVT. OF INDIA
Block No. 4, CGO Complex, Lodhi Road
New Delhi-110003


Crime Scene Examination Report

Report No: CFSL/DELHI/1648 /BIO/90/24/3289. Dated: 11. 09.2024






xli. It was conveyed to the CFSL Delhi team by the IO of this case that, the body of the victim was laying on the mattress placed on the wooden stage; Evaluated forensically by the team.



xlii. The bare mattress was having cut marks and some dirty stains; Evaluated forensically by the CFSL, Delhi team.



xliii. It was further conveyed by the IO of this case that these cut marks are due to cutting of blood-stained portions of the mattress by the SIT crime team for doing sample collection for forensic examination; and same cut portions were already forwarded for forensic examination; Evaluated forensically by the expert team.

xliv. The cut mark portions observed on this mattress were reasonably corresponding to the head and lower abdomen area of an injured-victim who happens to be laying on this mattress; IO was suggested to take the notice of it [as part of the investigation].

xlv. The 1st room (with two installed Window AC), described above, in which two walls were demolished was not housing any patient bed at the time of CFSL team' visit.

xlvi. Further, one side demolition was corresponding to gate-shape and other side demolition was unusual as functional electric peripherals was observed in demolished area wall.

xlvii. Further, the adjacent room of the 1st Room was having one-side demolished gate-shape area and patient beds, mattresses and furniture were dumped haphazardly in this room. No demolished concrete remnants were found in this room. Further, the room was in a scabby, dirty and highly unhygienic condition.


xlviii. The areas of Respiratory Care Unit Dept of Pulmonary Medicine of R G Kar Hospital were found in dirty condition.

(10)

CENTRAL FORENSIC SCIENCE LABORATORY
DIRECTORATE OF FORENSIC SCIENCE SERVICES
MINISTRY OF HOME AFFAIRS, GOVT. OF INDIA
Block No. 4, CGO Complex, Lodhi Road
New Delhi-110003

Crime Scene Examination Report

Report No: CFSL/DELHI/1648 /BIO/90/24/3289. Dated: 11.09.2024



Collection of left-over clue Materials by the CFSL Delhi expert Team: Victim' dead body was already shifted from the SOC @ R G Kar Medical College & Hospital Kolkata, and was stated to be cremated as well. SOC was already examined by the SIT team, the most probable evidences related to the crime under reference were stated to be already collected by the SIT team including the SOC area on the wooden stage. The SOC, above & below the stage area, table and the adjacent rooms were searched scientifically by the CFSL Delhi experts for presence of any left-over clue material[s] or their vital trace evidence[s].




(12)

CENTRAL FORENSIC SCIENCE LABORATORY
DIRECTORATE OF FORENSIC SCIENCE SERVICES
MINISTRY OF HOME AFFAIRS, GOVT. OF INDIA
Block No. 4, CGO Complex, Lodhi Road
New Delhi-110003

Crime Scene Examination Report

Report No: CFSL/DELHI/1648 /BIO/90/24/3289 **Dated: 11.09.2024**




CFSL Delhi team in search for left-over clue material[s] or their vital trace evidence[s]:

- SOC seminar hall, above & below the stage area, table and the adjacent rooms were thoroughly searched by the CFSL experts using appropriate scientific tools including high intensity multisource light for presence of any leftover logical clue material or their traces related to this case under reference; team could succeed in finding the following evidential materials:

a. A few long hair strands recovered from the wooden table' blue plastic sheet top [positioned on the wooden stage in seminar hall], near the place [where the hospital authorities told to CBI] the said crime occurred: marked as Exhibit-1 [do refer # xxxiii to xxxv; and # xxxvii to xl].
b. A few long hair strands recovered from the mattress positioned on the wooden stage: marked as Exhibit-2 [do refer # xxxii; and # xxxvii to xl].
c. A torn piece of medicine wrapper [name not clear] collected from close area of the wooden stage: marked as Exhibit-3 [do refer # xxxiv].
d. One mobile back cover collected from adjacent area of the wooden stage: marked as Exhibit-4 [do refer # xxxiv].
e. Fifteen numbers of torn document pieces having suspected handwritings collected from adjoining area of the wooden stage: marked as Exhibit-5 [do refer # xxxiv].
f. Suspected stain cuttings collected from mattress lying on the wooden stage: marked as Exhibit-B-1 [do refer # xxxii; and # xxxvii to xl].
g. Suspected stain cuttings collected from mattress lying on the wooden stage: marked as Exhibit-B-2 [do refer # xxxli; and # xxxvii to xl].

These clue materials [recovered from the seminar hall SOC area] were directly handed over to the IO of CBI of this case for further necessary action.






(29)

CENTRAL FORENSIC SCIENCE LABORATORY
DIRECTORATE OF FORENSIC SCIENCE SERVICES
MINISTRY OF HOME AFFAIRS, GOVT. OF INDIA
Block No. 4, CGO Complex, Lodhi Road
New Delhi-110003

Crime Scene Examination Report

Report No: CFSL/DELHI/1648 /BIO/90/24/.3289 **Dated: 11. 09.2024**



The CFSL experts then systematically examined the adjacent rooms of the seminar hall including the Doctor's rooms with partly demolished walls as described above for the possibilities of any left-over clue, its trail or any traces. The remnants of demolished broken bricks and tiles were scanned for presence of biological clue materials. However, no logical suspected biological materials related to the case could be detected from the adjacent rooms including the HODs room, library, and other doctor's rooms [do refer # xiii to xxxii].

CFSL Delhi expert minutely and forensically evaluated on the given inputs vis-à-vis left-over clues at the already examined and disturbed scene; the forensic observations were meditated upon critically to elude plausible forensic inference[s] [of relevance to the Investigation & Justice] are construed as underneath:

i. Except the mattress located on the wooden stage, no biological stains could be detected on, around, underneath the rest of wooden stage portion, wooden table with blue sheet top.

ii. Except the mattress located on the wooden stage, no biological stains could be detected on the floor surface in the seminar room which was stated to be the place of offence.

iii. The clue materials [hair strands, torn piece of medicine wrapper [name not clear], mobile back cover, fifteen numbers of torn document pieces having suspected handwritings recovered from the seminar hall SOC area and suspected stain cuttings collected from mattress lying on the wooden stage; by the expert team of CFSL, Delhi] were directly handed over to the IO of CBI of this case for further necessary action.

iv. The cut mark portions observed on this mattress that were reasonably corresponding to the head and lower abdomen area of an injured-victim who stated/happens to be laying on this mattress, however, the evidences of possible struggle shown by the victim to the assailant or fight in between them [in this case under reference] found missing in the shown area of occurrence i.e. wooden stage mattress and adjoining area inside the seminar hall.

v. There is less possibility that someone [in the presence of the official attendees present in the 24x7 operational hospital' corridor, doctor's duty-nursing station area] can enter into the seminar hall unnoticed, for committing offence.

11/09/2024	11/9/2024	11/9/24	11/09/2024	11.09.2024
(Mithilesh Jha)	(Anuj K. Bhati)	(P. K. Gottam)	(A. D. Tiwari)	(Dr. B. K. Mohapatra)
Sci-B [Biology]	A.D. (Finger Print)	D.D. (Photo)	D.D. (Photo)	D.D. (Biology)
Expert Member	Expert Member	Expert Member	Expert Member	Expert Team Head

Dr. B K Mohapatra
Deputy Director & Scientist 'D' (Bio)
Central Forensic Science Laboratory